

SPECIAL AIRWORTHINESS INFORMATION BULLETIN

Aircraft Certification Service
Washington, DC



U.S. Department
of Transportation

**Federal Aviation
Administration**

No. SW-04-13
November 7, 2003

www.faa.gov - Search "SAIBs"

This is information only. Recommendations aren't mandatory.

Introduction

This Special Airworthiness Information Bulletin advises you, owners and operators of **Schweizer Aircraft Corporation, model 269C rotorcraft**, equipped with an optional 269A4995 **throttle governor kit**, to inspect and possibly replace the throttle bellcrank, P/N 269A8418-21. We're also advising you that Schweizer has issued Service Bulletin B-281, dated September 5, 2003.

Background

Schweizer has received reports of two instances where the P/N 269A8418-21 bellcrank failed due to excessive wear leading to loss of throttle control. A redesigned replacement bellcrank has been available since 1996.

Reference Documentation

- Service Bulletin B-281
- Service Notice N-180

Recommendation

We recommend that you inspect the referenced bellcrank for wear as soon as possible, according to Schweizer's, Service Bulletin, B-281.

For Further Information Contact

Richard P. Fiesel, Aerospace Engineer, FAA New York Aircraft Certification Office, 10 Fifth Street, 3rd Floor, Valley Stream, NY 11581; phone: (516) 256-7504; fax (516) 568-2716; email: richard.fiesel@faa.gov

Schweizer Aircraft Corporation, 1250 Schweizer Rd., Horseheads NY 14845; phone: (607) 739-3821; fax: (607) 796-2488.